

Tom Love Innovation Hub Fabrication Lab User Checklist

Please read the following checklist before your first visit to the Fabrication Lab. Using this checklist will ensure a positive first experience.

- Bring at least one form of identification; University of Oklahoma ID or Driver's License is preferred.
- Consider reading our Frequently Asked Question page [here](#) before your first visit to the Fabrication Lab.
- Watch any applicable certification videos and complete attached certification quizzes before your first visit to the Fabrication Lab.
- Wear or bring an extra pair of closed-toe shoes and tight-fitting clothing when you visit the Fabrication Lab.
- Ensure you have brought all necessary materials for your project.
- If planning to use the laser cutters, quarter-inch birch plywood is recommended, which may be purchased from Home Depot, Lowes, and most other home improvement retailers or hardware stores.
- Please note, Fabrication Lab employees will inspect any material before use of the laser cutters and retain the right to deny use of the laser cutters if our employees deem the material improper.
 - Commonly rejected materials include, but are not limited to:
 - Certain wood materials, such as:
 - particle board
 - MDF
 - HDF
 - OSB
 - wood that is dirty
 - most reclaimed wood
 - most pine plywood
 - most underlayment plywood
 - Unidentified plastics. All plastics but be identified by type before use.
 - Polycarbonate sheet plastics, which are frequently confused with acrylics.